











Ra	nge of measurement	of measurement	
Sphere	0~±25D 0.01/0.12/0.25D step	0~±25D 0.01/0.12/0.25D s	
Cylinder	0-±10.00D 0.01/0.12/0.25D ste	0-±10.00D 0.01/0.12/0.25D	p
Axis	0*-180* (1*step)	0"~180" (1"step)	
Add.	0~+9.99D 0.01/0.42/0.25D step	0~+9.99D 0.01/0.12/0.25D	
Prism degree	0~15 \(\triangle 0.01/0.12/0.25D \text{ step} \)	0-15 △ 0.01/0.12/0.25D st	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Measurement mode	Measurement mo	
Cylinder	+,+/-,-	+,+/-,-	